H NO ONE NONE, USE 10CK SOK, 1967

ZANCOR Zancor Homes (Caledon) Ltd.
HOMES Phone: (905) 738-7010
Fax: (905) 738-5948

Closing Dato: 30Nov23
Address: 17 Gatherwood Terrace
Address: 17 Gatherwood Terrace
Caledon, Ontario L7C 4M5
Location: Caledon Club - Phase: 1B - Lot: 93B
Today's Date: 09Aug24
Contact(s): Hind Zid Haffer - Cell: (647) 472-9143 - (zaidhaffar91@gmail.com)
Email: zeidhaffar91@gmail.com

Zancor -Caledon

Attention: Telephone: Fax:

Please Complete the following items:

DAI	Туре	lssue	Appt. Date/Time	Notes
178215	Interval	Exterior- General- inspect water draining on upper porch - as per heemonwer When it's raining outside as you can see in the video the water is gathering, it seems like the drain on the entrance roof is not functioning properly. I'm afraid if we leave it to winter it will cause iolcles and not be able to handle the weight of snow if no one is home entre via lock box - 1967	15Aug24 /am	BOOK ZANCOK TRUDEL

Date Completed:

Date Completed:

Homeowner Signature:
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Trade & for Service Tech.

page 1 / 2

1 Tophera

-2000 - I OISKROI KINGSVIEW TO OFFER SUDFICE ISSUE OS WEIL. KINGS Phone: (905) 738-7010 Fax: (905) 738-5948

Location: Today's Date: Contact(s): Glosing Date: 02Aug23
Address: 15 Lippa Drive
Caledon L/C 4M3
Location: Caledon Club - Phase: 1B - Lot: 8B
Today's Date: 09Aug24
Contact(s): Vilaksh Bansal - Cell: (437) 230-2806 - (vilaksh89@gmail.com)
Yogita Bansal - Cell: (416) 417-3836 - (yobansal.44@gmail.com)
Wilaksh89@gmail.com

Zancor -Caledon

Company:
Attention:
Telephone:
Fax:

Plea
se Cc
mple
te the
folloy
l guly
tems:

DAI Type Issue	Туре	Issue		Appt.	Notes
177955	Interval	Bedroom 2- General- when they fixed the carpet trim chipped	F	15Aug24 /am	
177957	Interval	Other- General- patch on man door to be painted	6	15Aug24 7am	
177958	Interval	Foyer- General- Inspect humidity forming on main door knob - AS PER JESSE SAND AND PAINT REQUIRED	150	15Aug24	
178061	Interval	Main Hall- General- svc touch up baseboard-AS PER JESSE SAND AND PAINT REQUIRED	6	15Aug24 7am	
178062	Interval	Main Hall- General- Paint job on one of the front entrance door closet. AS PER JESSE SAND AND PAINT REQUIRED	FO	15Aug24 /am	

178204 Interval Max Ges JES	78082 Interval Mai
Master Bedroom- General- AS PER JESSE SAND AND PAINT REQUIRED	Main Bathroom- General- Yellow bleeding through at corner main bath
15Aug24 /am	/5Aug24 /am

Date Completed:

ited:

Homeowner Signature:
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Trade &/or Service Tech

Date Completed Huy

Signature:

Print Name: AddITTT

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Fallure to comply with this request within 10 business days will give Zancor Homes (and It's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Outstanding Deficiencies Caledon Club - Phase: 1B - Lot: 8B

<u>Date</u> Reported	Type	Number	Deficiency Description	Trade Assigned	Add Trade	Add Appointment Trade Date	Item Completed	
24Jun24	Interval	59	Exterior- General- downspouts 2 different colors	Promark Aluminum LTD. 177331	Add	15Aug24		10 11
09Jul24	Interval	60	Exterior- General- Edge of the foundation still did not fix edge of foundation not square	MCF Forming Contractors INC. 177660	Add	15Aug24		
09Jul24	Interval	61	Exterior-General-Brick got chipped on gas line in backyard -	River Valley Masonry Group LTD 177661	Add	15Aug24		
10Jul24	Interval	62	Foyer- General- dont door paint chip at exterior	Perfect Touch - CALEDON 177668	Add	15Aug24		
19Jul24	Interval	64	Exterior-General- we have recently used the outdoor switch on my backyard side and they are tripping it. I had to go to basement multiple times to reset that	Dart Electric 177815	Add	15Aug24		
22Jul24	Interval	65	Basement- General- Pipe to hvac has hole needs to be fixedHOLE	National Air 177847	Add	15Aug24	6	1
25Jul24	Interval	66	Bedroom 2- General- when they fixed the carpet trim chipped	Zancor - Caledon 177955	Add	15Aug24	10	1 - V
25Jul24	Interval	68	Other- General- patch on man door to be painted	Zancor - Caledon 177957	Add	15Aug24	B	
25jul24	Interval	69	Foyer- General- inspect humidity forming on main door knob - AS PER JESSE SAND AND PAINT REQUIRED	Zancor - Caledon 177958	Add	15Aug24	F	1 1
30Jul24	Interval	71	Master Ensuite- General- In master bathroom ensuite, for the standalone bath tub there is knocking sound while shutting the tap.	Icon Plumbing & Heating 178003	Add	15Aug24		
30JuJ24	Interval	72	Main Hall- General- svc touch up baseboard-AS PER JESSE SAND AND PAINT REQUIRED	Zancor - Caledon 178061	Add	15Aug24	F	
30Jul24	Interval	73	Main Hall- General- Paint job on one of the front entrance door closet .AS PER JESSE SAND AND PAINT REQUIRED	Zancor - Caledon 178062	Add	15Aug24	()	
02Aug24	Interval	76	Garage- General- garage hose bib leaking	Icon Plumbing & Heating 178080	Add	15Aug24		
02Aug24	Interval	77	Main Bathroom- General- Yellow bleeding through at corner main bath	Zancor - Caledon 178082	Add	15Aug24	(E)	
02Aug24	Interval	78	Other- General- ADJUST MAN DOOR AND FRONT FOOR WATER COMING INSIDE	<u>Newmar</u> 178083	Add	15Aug24		
02Aug24	Interval	79	Master Bedroom- General- AS PER JESSE SAND AND PAINT	Zancor - Caledon	Add	15Aug24	B	

lata/builderforms/ZanHSReportDeficiency/CheckList.php?&var_selected_app=PASS&var_Centre=Caledon Club&var_Pha... 1/2

8/9/24, 4:33 PM

80 REQUIRED
Bedroom 2- General- DIP IN
SUBFLOOR IN BEDROOM 2 CARPET Deficiency Check List - User: Alexandria Damie

1782.04

N-DIP IN

Kingsziew
EDROOM 2
1782.05

Add

1782.05

09Aug24 Interval

15Aug24

Homeowner Signature:

Zancor Service Technician: The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction. BUTTEN

ONNTIME - EXTERIC ONLY HERECURE WILL NOT LES HOMES Phone: (905) 738-5948

Contact(s): Celledon Club - Phase: 15 Lot: 15B

Contact(s): Reuben Javis Fernandes - Cell: (416) 880-7365 - (reuben.fernandes@gmail.com)

Kalarzyna Fernandes - Cell: (403) 803-1422 - (kalina.m.fernandes@gmail.com)

Zancor - Caledon

Company Attention: Telephone:

Please Complete the following items:

DAI	Туре	İssue	Appt. Date/Time	Notes
177614	1 Year	Exterior- General- Insufficient gravel in some window wells- SITE	14Aug24 /am	3. K.
77040				
177616	1 Year	Exterior- General- Patio stone cracked at side door	14Aug24 /am	公方:
177629	1 Year	Other- General- Crack in wood casing on the exterior side of garage door (lower left side) - door to paint touch ups	14Aug24 /am	DOWE

Date Completed:

Date Completed Pull

Homeowner Signature:
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Trade &/or Service Tech.

Print Name: KOCI HER

Signature:

page 1 / 2

Outstanding Deficiencies Caledon Club - Phase: 1B - Lot: 108B

	4 4 6 6	3 6 3	
ZESSUITE-General-RE/RE RG AT TUB WALL- tile RG AT TUB RG AND RESERVED AT TUB RG AT TUB RG AND RESERVED AT T	2 Ensuring General - RE/RE AV Cla 1763 Enough From the Clark of the Clark REPARS of the Clark of the Clark of the Clark REPARS of the Clark of the C	Z Eusuite-General-RE/RE NG AT TUB WALL-tile NG AT TUB WALL-tile NG AT TUB WALL-tile 17638 seneral-remove scuff at px2-unable to remove- 17638 enteral-Dented copping at Trudel & Senetary New Bedroom window (CK REPAIRS) CK REPAIRS 177077 eral-remove paint spra on Zancor-Cal	Z Ensuire-General-RE/RE AV Class VG AT TUB WALL- tile AV Class encral- remove scuff at p x2 - unable to remove- 176382 iencral- Dented copping at low bedroom window(177077 etral- remove paint spra on Zancor-Cale 177077 etral- adjust front foor AV Class 177077 177707 177707
LKING AT TUB WALL tile 211 Care General remove souff at tild dap x2 - mable to remove - 17638 22 till Care Till WALL tile 17638 23 till dap x2 - mable to remove - 17638 24 till Care	LKN/G AT TUB WALL- tile 211 212 213 214 216 21763 227 228 239 240 261 276 276 276 276 276 276 276	LKING AITUB WALL tile 2011 Carrow souff at this day 22 - unable to remove - 1763. 2014 Carrow bedroom window (1704) EPARS 1181CK REPARS 1700 - General- remove paint spra on 22000 Carrow - 21700 Car	LKING AT TUB WALL tile 211 LKING AT TUB WALL tile 217 218 219 219 210 210 210 210 210 210
tichen- General-remove souff at le with dap x2 - unable to remove - 17638 splace tile with dap x2 - unable to remove - 17638 waterior- General- Dented copping at Trudel & Andrew (17707	tichen- General- remove souff at le with day x2 - unable to remove - 17633 place tile with day x2 - unable to remove - 17633 xxierior- General- Dented copping at 1704 & 200 M BRICK REPAIRS	titchen- General- remove souff at le with day x2 - unable to remove - 1763, place tile place tile yet deform window(1700M BRICK REPAIRS 11700 Paints General- remove paint spra on 22000 Celets	tichen-General- remove scuff at le with day x2 - unable to remove - 1763 place tile with day x2 - unable to remove - 1763 xderior- General- Dented copping at Thidel 2 (XoOM BRICK, REPAIRS) 2001 Size General- remove paint spra on Zencor - Celetis Typer-General- adjust front foor 1777
Exterior- General- Dented copping at Tradel & Indented Communication of Below bedroom window(Room BRICK REPAIRS 17707	a on at	Exterior- General- Dented copping at Thudel & flat roof below bedroom window(Roofing. ROM BRICK REPAIRS 17707 Stairs- General- remove paint spra on Zencor-Copickets	Exterior- General- Dented copping at Thodel. & Rooting filat roof below bedroom window(1770 States-General- remove paint spra on Zancor-C pickets Terror foor 1770 Poyer- General- adjust front foor 1777
flat roof below bedroom window(Roofing I 17707	Hat roof below bedroom window(ROM BRICK, REPAIRS Stairs—General- remove paint spra on Zanco-Co pickets 17707	Hat roof below bedroom window(1ROM BRICK REPAIRS Stairs- General- remove paint spra on Zancor -C; pickets 17707	Bat roof below bedroom window(ROM BRICK, REPAIRS Stairs- General- remove paint spra on Zancor-C pickets Foyer- General- adjust front foor 1770 1777
2			

Homeowner Signature

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: Hull H CH

Zancor Service Technician:

Outstanding Deficiencies Caledon Club - Phase: 1B - Lot: Block 196 - Unit 5

Reported 25Mar/24		Number 2		D Property of the Property of	Assigned Perfect Touch	Add Trade	를 집	Add Appointment Item Trade <u>Date</u> Completed
25Mar24	4 Interval	al 7	Stairs- General- stain touch ups required due to Bolton repairs	ouch ups repairs	Perfect Touch - CALEDON 174677	区后	Add Add	Add 15Aug24
23Apr24	4 30-Day	y 17	Den-General- significant temperature difference between second and first floors-air balance required	unt temperature ond and first red	National Air 175664	Fi.	Add	_
23Apr24	4 30-Day	у . 21	Kitchen- General-glue or stains and small chip / hole on the countertop-inspect	or stains and a countertop-	Redstone Marble 175668		Add	Add 15Aug24
23Apr24	4 30-Day	y 28		y holes or pits	Redstone Marble 175675		Add	Add 15Aug24
23Apr24	Interval	9	Throughout- General- grain tape touch ups throughout- G inspected and confirmed - as per Jesse - first floor landing celing - sand and paint required	rain tape touch ected and - first floor d paint	Zancor - Catedon 175682		Add	Add 15Aug24
07Aug24	Interval	13	Stairs- General- stain required due to bolton repair		Perfect Touch - CALEDON 178177		N Add	

Homeowner Signature:

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: Hug 15/24
Zancor Service Technician:

1/1