Outstanding Deficiencies Caledon Club - Phase: 1B - Lot: Block 196 - Unit 1

Aug 14#

ĺ								
		<u>25Jul24</u>	Add	Perfect Touch - CALEDON 175802	Stairs- General- At the very top of the stair/step there is a really large dent as indicated by take that needs to be rebuffed and filled.	20	30-Day	29Apr24 30-Day
		<u>25Jul24</u>	Add	Perfect Touch - CALEDON 175801	Stairs- General- The wall up the stairs Perfect Touch have several dents that need to be sanded, buffed and repainted 175801	19	29Apr24 30-Day	29Apr24
	Item Completed	Add <u>Appointment</u> Trade <u>Date</u>	Add Trade	Trade Assigned	Deficiency Description	Number	Туре	<u>Date</u> <u>Reported</u>

See	STA AT
Ras	3
2	9
	CKET
MERCH	700

AND to 3rd STAIN REPAIRS

Homeowner Signature:	

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Zancor Service Technician:

Date:

MAIN FLOOR 1304317 POWDER / MAIN BATH

OVERHEAD GARAGE DOOR RUBS ON TRACK

IN GARAGE

CHIP ON FRONT

CANTINA DRAIN