

- GARAGE SLIDE OUT SHELVING
- FRONT STEPS PITTED NEED TO BE CHANGED AND CLEAN SCARS - 2/ VAL GREEN

#8 - PAINT GARAGE FRAME + JOINT ON HARDY @ PORCH
 - CAULK POST TRIM TO HARDY BOARD - ZAUOK
 - MORTAR JOINT SETTLEMENT @ RECAST ABOVE GARAGE

#42 - 45 - SOME HARDWOOD JOINTS ARE BUCKLING

- KITCHEN COUNTER TOPS CHIP/PIT
 - SUBCONE / TILE @ STAIRS INTO KITCHEN (TILE CUT SHORT)
 #53 - MATTARY INFO? (MANUELS) (4 COVER w/ TRIM)

#85 - STAIRS - STRUCKER UNDER NOISING
 - TOP TREND @ 2nd FLOOR / NOISING @ 2nd FLOOR
 - PICS FROM STAIR CUR

#55 - H/O WAS TOLD THE CARPET WOULD BE CHANGED
 4 ALREADY CLEANED

- MASTER ENSUITE - CAULKING UNDER GLASS BIG GAP BETWEEN MARBLE JAMB AND GLASS
 - CAULKING / RESAUE ON INSIDE GLASS

- A/C / FURNACE - AIR BALANCE - NATIONAL

- BUT ON OPT. BALCONY DOOR BY MIDDLE HUBBLE

- METAL CORPUS BENTED @ FRONT BALCONY