

Fri Sept 13 8am-3pm - Bring all parts*

ZANCOR
HOMES

Zancor Homes (Caledon) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 11Dec23
Address: 7 Gatherwood Terrace
Caledon, Ontario L7C 4M4
Location: Caledon Club - Phase: 1B - Lot: 98B
Today's Date: 10Sep24
Contact(s): Jagdeep Singh Kullar - Cell: (647) 989-9200 - (jagkullar92@gmail.com)
Email: jagkullar92@gmail.com
Company: Icon Plumbing & Heating
Attention:
Telephone: (647) 526-0027
Fax:

Please Complete the following items:

| DAI | Type | Issue | Appt. Date/Time | Notes |
|--------|----------|---|-----------------|-------|
| 177445 | Interval | Main Bathroom- General- water leak in washroom Master Ensuite- General- leak maybe at cartridge -leaking again after it was replaced - NATHAN INSPECTED ON AUG 22- ADVISED MAY BE THE FITTINGS - UPGRADED PLUMBING. WATER DAMAGE IN CLOSET - SVC TO CUT DRYWALL - need diviete + posi cartridge leaking | 04Sep24 /am | |

Date Completed: _____

Homeowner Signature: _____
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: _____

Trade &/or Service Tech.

Signature: _____

page 1 / 2

CARTRIDGES CHANGED + MORE
SOLDER APPLIED.

POSSIBLE DEFECTIVE/BROKEN
DIVERTER??

POST

U36ICE

100%
DWTW

~~1/11/24~~
~~1/11/24~~
~~1/11/24~~
~~1/11/24~~



Zancor Homes (Caledon) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 11Dec23
Address: 7 Gatherwood Terrace
Caledon, Ontario L7C 4M4
Location: Caledon Club - Phase: 1B - Lot: 98B
Today's Date: 16Sep24
Contact(s): Jagdeep Singh Kullar - Cell: (647) 989-9200 - (jagkullar92@gmail.com)
Email: jagkullar92@gmail.com

Company: Icon Plumbing & Heating
Attention:
Telephone: (647) 526-0027
Fax:

Please Complete the following items:

| DAI | Type | Issue | Appt. Date/Time | Notes |
|--------|----------|--|--------------------|--|
| 177445 | Interval | Main Bathroom- General- water leak in washroom Master Ensuite- General- leak maybe at cartridge -leaking again after it was replaced - NATHAN INSPECTED ON AUG 22- ADVISED MAY BE THE FITTINGS - UPGRADED PLUMBING. WATER DAMAGE IN CLOSET - SVC TO CUT DRYWALL - need diviete + posi cartridge leaking | 04Sep24 /am | <i>Done</i> <i>Replace</i> <i>diverter</i> <i>body</i> <i>100%</i> <i>Done</i> <i>B.</i> |

Date Completed: _____

Homeowner Signature: _____
The Homeowner acknowledges and accepts all work
has been completed in a workman like manner.

Date Completed: _____

Trade &/or Service Tech.

Signature: _____