ANCO HOMES Z

Zancor Homes (Wasaga River) Ltd. Warranty Services
Phone: (905) 738-7010 RRIVER

Work Order

Fax: (905) 738-5948

Address: Closing Date:

Location: 08Sep23
157 Rosanne Circle
Wasaga, Ontario
Rivers Edge - Phase: 1 - Lot: 255

12Sep24

Today's Date: Contact(s): Jessenia Mendez (2nd H/O) - Home: (416) 388-2327 - (canaras@live.ca) Albert Mendez - (albert.a.mendez@hotmail.com)

Email: canaras@live.ca

Wasaga Zancor Warranty Service

Companya
Attention:
Telephone: Fax (705) 428-6483 (705) 428-6484

Please Complete the following Items: 178722 178720 DA 178723 2 Year 2 Year 2 Year Type culking done improper, ceiling not painted. *
Bathroom 2: culking ceiling not painted.

Missing trim by the window. done improper and ceiling not painted. ssue Foyer- General- Front done improper and *bathroom 2: culking bathroom: culking Other- Generaland complete Culking around is needed.- svc inspect trim damaged. of the home entrance windows. * Front door done improper and missing trim by the Other- General- *
Connecting bathroom: *Connecting 20Sep24 /am /am 20Sep24 20Sep24 Date/Time Appt. Notes Done

		Date Completed:	Date Completed:	home entrance frame trim damage-svc inspect
Print Name:	Signature:	Trade &/or Service Tech.	Homeowner Signature: The Homeowner acknowledges and accepts all work has been completed in a workman like manner.	/am

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and It's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Outstanding Deficiencies Rivers Edge - Phase: 1 - Lot: 255

10Sep24	10Sep24	10Sep24	10Sep24	10Sep24	31Jul24		Date Reported
2 Year	2 Year	2 Year	2 Year	2 Year	Interval	Interval	Type
Ú.	4	ω	2	brest	55	7	Number
Main Hall- General- Fire alarm defective	Foyer- General- Front home entrance frame trim damage-svc inspect	Other- General- *Connecting bathroom: culking done improper and ceiling not painted. *bathroom 2: culking done improper and ceiling not painted. Missing trim by the window.	Master Bedroom- General- AC not cooling the master bedroom	Other- General- * Connecting bathroom: culking done improper, ceiling not painted. * Bathroom 2: culking done improper and missing frim by the windows. * Front door of the home entrance trim damaged. * Culking around is needed svc inspect and complete	Master Ensuite- General- grout required throughout shower - lots of holes thorughout	Kitchen- General- ISLAND COUNTER LOOSE (CAN LIFT UP OFF PLYWOOD)	Deficiency Description
Mykon Electric North Ltd 178724	Wasaga Zancor Warranty Service 178723	Wasaga Zancor Warranty Service 178722	National Air 178721	Wasaga Zancor Warranty Service 178720	AV Classic 178060	Redstone Marble 176144	Trade Assigned
Add	Add	Add	Add	Add	Add	Add	Add Trade
20Sep24	208cp24	20Sep24	20Sep24	20Sep24	15Aug24	15Aug24	Add <u>Appointment</u> Trade <u>Date</u>
		(8	*	Ltem Completed
The state of the s	B	AND	200	E.	*	X	Initial

Zancor Service Technician:	Date:	mamer to their satisfaction.	initialled work has been completed in a workman like	The Homeowner acknowledges and accepts that all

Homeowner Signature: