S GROUNDE A. DISPUBLIES OF MITTER

ANCOR HOMES

Zancor Oakville Ltd. Warranty Services

Phone: (905) 738-7010 Fax: (905) 738-5948

Work Order

Closing Date: 08Nov23

Address: 2450 Old Bronte Road, Suite 710

Oakville, Ontario

Location: The Branch Condos - Phase: 1 - Lot: 710

Today's Date: 26Nov24

Contact(s):

Bana OTAKI - Cell: (647) 764-3223 - (banaotaki@gmail.com)
Rami ALBAROUDI - Cell: (437) 345-9765 - (ramialbaroudi@gmail.com)

banaotaki@gmail.com

Email:

Branch-Service

Company:
Attention:

Telephone:

Please Complete the following items:

1)	
	02Dec24 /am	<	Master Bedroom- General- Paint blotch on bedroom door, interior	Interval	179599
·	02Dec24 /am	2	Living Room- General- Crack in wall next to entrance	Interval	179598
	02Dec24 /am		Living Room- General- paint blotch, right wall corner next to laundry room door	Interval	179597
	02Dec24 /am	-	Living Room- General- patch on wall next to master not finished	Interval	179596
	02Dec24 /am	5	Bedroom 2- General- Crack at door handle	Interval	179594
Notes	Appt. Date/Time	-	Issue	Type	DAI

Date Completed: Dec 4/24

Dec 4/24

Date Completed: _

Homeowner Signature:

has been completed in a workman like manner. The Homeowner acknowledges and accepts all work

Trade &/or Service Tech.

Signature:

Print Name:

e Jesse Simas

appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. Please schedule your Service Department to complete work on the above Lot. Should no

applied to the Company listed above. Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be


The Branch Condos - Phase: 1 - Lot: 710

179596 - 1 - 17 - patch on wall next to master not finished



to laundry room door 179597 - 1 - 17 - paint blotch, right wall corner next





Outstanding Deficiencies The Branch Condos - Phase: 1 - Lot: 710

Date Reported	Туре	Number	Deficiency Description	Trade Assigned	Add Trade	Add Appointment Prade Date	Item Completed	Initial
19Nov24	Interval	ر. د	Bedroom 2- General- Crack at door handle	Branch-Service 179594	Add	02Dec24		Asis
19Nov24	Interval	6	Bedroom 2- General- mulin short left of window	NEWMAR-The Branch 179595	Add	02Dec24		73
19Nov24	Interval	7	Living Room- General- patch on wall next to master not finished	Branch-Service 179596	Add	02Dec24	<	ASR
19Nov24	Interval	88	Living Room- General- paint blotch, right wall corner next to laundry room door	Branch-Service 179597	Add	02Dec24		ASS
19Nov24	Interval	9	Living Room- General- Crack in wall next to entrance	Branch-Service 179598	Add	02Dec24		7
19Nov24	Interval	10	Master Bedroom- General- Paint blotch on bedroom door, interior	Branch-Service 179599	Add	02Dec24	<	7
19Nov24	Interval	pA A	Laundry Room- General- water shut off cover still not installed from PDI	Malfar Mechanical Inc. 179600	Add	02Dec24		
19Nov24	Interval	12	Laundry Room- General- Gap between living room flooring and bathroom door threshold, gap shifts with floor movement	EIRST CANADIAN - THE BRANCH 179601	Add	02Dec24	and a management of the state o	Total deli secondo del secondo

Hc
meowner
Signature:
ł

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: L4
Zancor Service Technician: