T POO

Outstanding Deficiencies Caledon Club - Phase: 1B - Lot: 61B

06Aug24	<u>Date</u> Reported		
I Year	Туре		
4	Number		
Foyer- General- Front door was replaced, and not painted for a long time. The paint job done on the front door is terrible and needs cleaning / fixing and likely new paint job to be done	Deficiency Description Foyer- General- Front door was		
Perfect Touch - CALEDON 178090	Trade Assigned		
Add	Add A		
10Dec24	Appointment Date		
	Item Completed		
The state of the s	Initial		

Homeowner Signature:

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Zancor Service Technician:

TOIN to (3) She loooked this



ANCOR HOMES

Work Order

Fax: (905) 738-5948

Zancor Homes (Caledon) Ltd. Warranty Services
Phone: (905) 738-7010

Closing Date:
Address:

Location: 14Nov23 82 Camino Real Drive Caledon, Ontario L7C 4L9 Caledon Club - Phase: 1B - Lot: 155B

Today's Date: 02Dec24

Contact(s): Jatinder Pal S Sudan - Cell: (647) 878-1686 - (jpsudan73@gmail.com) Sandeep K Sudan - (sandysudan@gmail.com)

Email: jpsudan73@gmail.com

Company:
Attention: Zancor -C: ledon

Telephone:

Fax:

Please Complete the following items:

DAI	179737	179739	179740
Туре	1 Year	1 Year	1 Year
Issue	Main Bathroom- General- Shared Ensuite - Shower plumbing not installed correctly, door hard to open as it touches shower and tap upon opening, safety hazard, builder advised of the issue- NA	Kitchen- General- Floor produces vibrations when walked on, shakes abnormally-SVC	Family Room- General- Floor produces serious vibrations when walked on, items on kitchen island shake (Items brought to the builder attention
Appt. Date/Time	10Dec24 /am	10Dec24 /am	10Dec24 /am
Notes		BOOK ZAN	Back Zanca
		1,000	

179745	179744	179743	179742	179741	
1 Year	1 Year	1 Year	1 Year	1 Year	
Exterior- General- Garbage over Shingles not cleaned, builder advised multiple times	Master Bedroom- General- Creaking and squeaking in all bedrooms have drastically increased even when taking light steps	Main Hall- General- Newly repaired hardwood piece joint uneven	Stairs- General- Incessant creaking on steps on Level 1 to Level 2	Main Hall- General- Baseboard uneven & poorly finished in front of first floor (main level) washroom	multiple times, left for year end)-SVC
- APP	76	è	1	1/2	
10Dec24 /am	10Dec24 /am	10Dec24 /am	10Dec24 /am	10Dec24 7am	
RIVER VALLEY		KEDIRACE FOH			

Date
Cor
nple
ted:

Homeowner Signature: X

has been completed in a workman like manner. The Homeowner acknowledges and accepts all work

Date Completed:

Trade &/or Service Tech

Signature:

Print Name:

signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. adhere to the appointment you have scheduled. Your service representative must have this form appointment time or date appear (below) on this form, it is your responsibility to arrange and Please schedule your Service Department to complete work on the above Lot. Should no

applied to the Company listed above. it's group of companies) the right to carry out any and all repairs. All costs incurred will be Failure to comply with this request within 10 business days will give Zancor Homes (and