Enrollment:

Phone Res:

Purchaser Name: Walter Chavez

ZANCOR HOMES PDI

Page 1 of 2

Vendor / Builder:

Project: Zancor Homes (Wasaga River) Ltd

Lot / Phase: 66 / 2

Plan:

Address: 52 Rosanne Circle

Municiaplity:

Inspection Date: December 17, 2024

Phone Bus: (647) 975-3663 **Closing Date:** February 06, 2025

Inspector: Gisella Fiore

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- · Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- · Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- · Faucets: Kitchen, bathroom, laundry room
- · Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- · Gas fireplaces, incl.circulation fans, if provided
- · Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- · Air conditioning system, if provided and if conditions permit

BEDROOM 3 ENSUITE				
NOTE:	RAISE CARPET AT ENTRANCE TO BATH			
KITCHEN				
CABINETS	CHIP AT BOTTOM GABLE AT ISLAND LEFT SIDE. INSIDE CABINET			
FOYER/HALL				
STAIRS	SCRATCH ON 2ND TREAD AT STAIR FROM MAIN TOP 2ND FLOOR			

Enrollment:

Purchaser Name: Walter Chavez

ZANCOR

Vendor / Builder:

Project: Zancor Homes (Wasaga River) Ltd.

Lot / Phase: 66 / 2

Plan:

Address: 52 Rosanne Circle

Municiaplity:

Inspection Date: December 17, 2024

 Phone Res:
 (647) 975-3663

 Closing Date:
 February 06, 2025

Inspector: Gisella Fiore

Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Walter Chavez	A hope		
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
		Gisella Fiore	SHE
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature