

Outstanding Deficiencies
Rivers Edge - Phase: 2 - Lot: 63
Permission To Enter: Bondi (50-08) Elev D

Date Reported	Type	Number	Deficiency Description	Trade Assigned	Add Trade	Appointment Date
06Jan25	PDI	1	BEDROOM 3 ENSUITE- MIRROR~DENT ON METAL T MOLD AT ENTRANCE TO BATHROOM. 	AV Classic 180204	Add	NoAppoint.
06Jan25	PDI	2	FOYER/HALL- STAIRS~MISSING STAIN AT TRIM LEFT OF NOSING AT 2ND FLOOR 	Perfect Touch Painting 180205	Add	NoAppoint.
06Jan25	PDI	3	FOYER/HALL- STAIRS~EXPOSED SCREW BELOW RISER AT 2ND FLOOR 2) GAP AT NOSING RIGHT OF STRINGER AT NEWEL POST BELOW. 	Bolton Railings Inc. 180206	Add	NoAppoint.
06Jan25	PDI	4	FOYER/HALL- FLOORING~POUR CUT JAMB LEFT SIDE AT DOOR WAY TO MAN IN FLOOR FROM MUD ROOM AT NOSING 	WYECROFT TRIM 180207	Add	NoAppoint.
06Jan25	PDI	5	FOYER/HALL- FLOORING~GAP AT TRIM AND TILE AT STAIRS TO MAIN FLOOR FROM GARAGE ENTRANCE 	Wasaga Zancor Site Labour 180208	Add	NoAppoint.
06Jan25	PDI	6	FOYER/HALL- FLOORING~MISSING GROUT AT REGISTER RIGHT OF MAN DOOR. 	AV Classic 180209	Add	NoAppoint.
06Jan25	PDI	7	KITCHEN- CABINETS~UPPER FILLER RIGHT OF SINK TO BE SECURED AT CORNER CABINET 	New Image Kitchens 180210	Add	NoAppoint.
06Jan25	PDI	8	KITCHEN- CABINETS~GABLE SHORT LEFT OF SINK FACING LIVING ROOM. 	New Image Kitchens 180211	Add	NoAppoint.

Tread overcut @ posts @ main floor (1st set to 2nd)

Homeowner Signature: 

I hereby acknowledge and accept