

Pre-Delivery Inspection Form

Unit Enrolment #

124B - CHEBON.

Item #	Room/Location	Description
NO 1	STAIRS	CLEAN PAINT OFF SPINDLES THROUGHOUT
PS 2	" "	STAIRS @ MAIN TO 2ND Squeaking
PS 3	" "	Exposed staples @ riser below nosing @ 2nd Floor
NO 4	" "	LINE @ 5th Rise @ STAIRS FROM main to landing to 2nd (STAIN)
PS 5	" "	STAIN missing @ Plug @ SHORT Railing facing dining Room
PS 6	Foyer	- Damage @ Right door trim interior @ bottom
NO 7	" "	ADJUST MAIN DOOR NOT CLOSING.
NO 8	KITCHEN	Back Panel centered @ screw @ upper right cabinet Right of stove

List here anything that can't be assessed, because for example it is obscured from view, missing or inaccessible.

Item #	Room/Location	Description
PS 9	KITCHEN	ADJUST SLIDING DOOR.
NO 10	SEASONAL - *SPRING* EXTERIOR	- POWER WASH Required left side
PS 12	" "	- Inspect x3 Brick chipped left of side entrance.
PS 13	" "	- Inspect x2 gaps @ make a mark above sliding door
PS 14	" "	- Secure light Right of Garage

X Paul H. H. H.