Enrollment:

Purchaser Name: Logan Phillips

Manish Taneja

Phone Res:

Phone Bus: (705) 791-3933 **Closing Date:** March 19, 2025

Inspector: Gisella Fiore

ZANCOR HOMES PDI

Vendor / Builder:

Project: Zancor Homes (Wasaga River) Ltd

Lot / Phase: 337 / 1

Plan:

Address: 77 Sun Valley Crescent

Municiaplity:

Inspection Date: March 06, 2025

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

Page 1 of 2

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- · Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- · Interior finished and trim carpentry
- Furnace
- · Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- · Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- · Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- · Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MASTER ENSUITE	ВАТН	
WALLS	MISSING GROUT INSIDE SHOWER BELOW JAMB AT DOOR FILLED WITH	
	SILICONE	
	CHIP AT LEFT COUNTERTOP SIDE SPLASH	
MAIN BATHROOM		
MIRROR	DAMAGED MIRROR LEFT CORNER.	
FOYER/HALL		
FLOORING	CRACKED GROUT/ OVER CUT AT NEWEL AT MAIN FLOOR.	
STAIRS	STAIN REQUIRED AT RAILING AT STAIRS TO MAIN FLOOR	
	STAIN REQUIRED AT NOSING AT STAIRS TO BASEMENT LEFT SIDE	
	FILL CRACK AT NOSING THAT OPENED AT STAIRS TO BASEMENT.	
	SANDING REQUIRED AT TRIM AT WINDER STEP FROM BASEMENT TO MAIN	
	FLOOR	
NOTE:	ADJUST MAN DOOR TO GARAGE, NOT CLOSING	
EXTERIOR		
NOTE:	HOMEOWNER UNHAPPY WITH CAULKING AROUND LIGHT FIXTURE IN GARAGE	
	NOTED ON REPORT.	
	NO VISIBLE WEEP HOLES (SMALL OPENINGS IN BRICK WALL MORTAR JOINTS)	
	NOTED ABOVE THE LEFT SIDE WINDOW OPENING(S). RECOMMEND	
	INSTALLATION AS REQUIRED. REFERENCE CPG 4.18 (AS PER REPORT NOTED	
	ON PURCHASE CONFIRM IF COMPLETED)	
BASEMENT		
-	AS PER INSPECTION REPORT, WALL, STUD, REMOVED AT PLUMBING SACK,	
	CONFIRM IF REQUIRED.	

Enrollment:

Purchaser Name: Logan Phillips

Manish Taneja

Phone Res:

Phone Bus: (705) 791-3933
Closing Date: March 19, 2025
Inspector: Gisella Fiore

ZANCOR HOMES PDI

Page 2 of 2

Vendor / Builder:

Project: Zancor Homes (Wasaga River) Ltd.

Lot / Phase: 337 / 1

Plan:

Address: 77 Sun Valley Crescent

Municiaplity:

Inspection Date: March 06, 2025

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Logan Phillips Manish Taneja

Purchaser's Name (print) Purchaser's Signature Purchaser's Name (print) Purchaser's Signature

Kun Palipo Gisella Fiore

Designate's Name (print) Designate's Signature Inspector's Name (print) Inspector's Signature