Enrollment: 338

Purchaser Name: SONYA PIERRETTE DUARTE

FRANK DUARTE

Phone Res: (647) 990-0068 Phone Bus: (289) 221-9622 Closing Date: May 30, 2025 Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (King Cort) Ltd.

Lot / Phase: 338 / 1

Plan:

Address: 2075 King Road, Unit 338

Municiaplity:

Inspection Date: May 22, 2025

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN		
NOTE:	CHIP ON FRIDGE GABLE LEFT SIDE TOP AND BOTTOM	
	CHIP ON UPPER LEFT CABINET RIGHT OF MICROWAVE.	
	UPPER BLOCKING MISSING AT CORNER CABINET	
	MISSING HANDLE AT UPPER LEFT CABINET LEFT OF MICROWAVE	
	FILM ON CABINET EDGES THROUGHOUT	
	INSPECT UPPER CABINET ABOVE SINK HANDLE RIGHT SIDE FURTHER THEN LEFT SIDE 2)	
	ADJUST CABINETS THROUGHOUT NOT STRAIGHT 3) KICKPALTE BELOW SINK MISSING RIGHT	
	HOOK	
MAIN BATHROOM		
NOTE:	CRACKED TILE RIFGHT OF FACUET AT WALL TILE.	
	ADJUST TOLIET SEAT	
	INSTALL BLACK BATHROOM ACCESSORIES - TOWEL RACK RIGHT OF SHOWER. TOILET PAPER HOLDER ON WALL.	
	FLOOR DRAIN SHOULD BE BLACK AS PER EXTRAS.	
LAUNDRY ROOM		
NOTE:	WRONG GROUT COMPLETE AT FLOOR TILE	
MASTER BEDROOM		
NOTE:	ADJUST WINDOW NOT CLOSING	
LIVING ROOM		
NOTE:	DENT ON BALCONY TRIM AT FLOOR TACK	
	TORN WINDOW SCREEN	
FOYER/HALL		
NOTE:	ADJUST DOOR AT CLOSET SQUEAKING	

Enrollment: 338

Purchaser Name: SONYA PIERRETTE DUARTE

FRANK DUARTE

Phone Res: (647) 990-0068 Phone Bus: (289) 221-9622 Closing Date: May 30, 2025

Inspector: Gisella Fiore

ZANCOR

Page 2 of 2

Vendor / Builder:

Project: Zancor Homes (King Cort) Ltd.

Lot / Phase: 338 / 1

Plan:

Address: 2075 King Road, Unit 338

Municiaplity:

Inspection Date: May 22, 2025

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS

A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the

designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

SONYA PIERRETTE DUARTE FRANK DUARTE

Purchaser's Signature Purchaser's Name (print) Purchaser's Name (print) Purchaser's Signature

Gisella Fiore

Inspector's Name (print) Designate's Name (print) Designate's Signature Inspector's Signature

May 22, 2025 Date (YYYY/MM/DD) 2025/05/22