Enrollment: 320

Purchaser Name: Harmanpreet S Shahi

2647746 ONTARIO INC

Phone Res: (647) 272-7443
Phone Bus: (647) 272-7443
Closing Date: June 24, 2025
Inspector: Gisella Fiore



Page 1 of 2

Vendor / Builder:

Project: Zancor Homes (King Cort) Ltd.

Lot / Phase: 320 / 1

Plan:

Address: 2075 King Road, Unit 320

Municiaplity:

Inspection Date: June 18, 2025

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN		
NOTE:	SCRATCH AT ON UPPER RIGHT AND LEFT CABINET RIGHT OF SINK	 
	REPLACE BOTTOM HANDLE RIGHT OF SINK	 
	CHIP ON FREEZER PANEL/ SCOFF AT GABLE GABLE SIDE.	 
	CRACK ON BACKSPLASH AT OUTLET LEFT OF STOVE.	 
-	ADJUST FACUET MOVING.	 
MAIN BATHROOM		
-	CONCRETE INSIDE TUB BELOW FAUCET.	 
	TUB STOPPER NOT INSTALLED.	 
LIVING ROOM		
-	ADJUST SCREEN DOOR NOT LOCKING	

Enrollment: 320

Purchaser Name: Harmanpreet S Shahi

2647746 ONTARIO INC

Phone Res: (647) 272-7443
Phone Bus: (647) 272-7443

Closing Date: June 24, 2025 Inspector: Gisella Fiore ZANCOR HOMES Vendor / Builder:

Project: Zancor Homes (King Cort) Ltd.

Lot / Phase: 320 / 1

Plan:

Address: 2075 King Road, Unit 320

Municiaplity:

Inspection Date: June 18, 2025

Page 2 of 2 Inspe

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

\* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate. Harmanpreet S Shahi 2647746 ONTARIO INC Purchaser's Name (print) Purchaser's Name (print) Purchaser's Signature Purchaser's Signature Gisella Fiore Designate's Signature Designate's Name (print) Inspector's Name (print) Inspector's Signature Date (YYYY/MM/DD) 2025/06/18 June 18, 2025