

Inspection Form - Pre-delivery Inspection**Report # INS000001**

Phase	The Social Condos	Site Super	
Lot	35Z	Closing Date	09/25/25
Model	KST-712-C	Enrollment No.	
Civic Address	, Caledon, , Ontario		
Inspector	Gisella Fiore	Date Inspected	07/16/25

--

#	House Area	Details of damage or defect
1	ALL HOUSE	AC NOT WORKING

All the above items have been reviewed and complited

Gisella Fiore

07/16/25



Inspector Name

Inspector's Signature

Prabhjot brar

07/16/25



Purchaser Name

Purchaser's Signature

Purchaser Name

Purchaser's Signature

Designate Name

Designate's Signature

Super's Signature

Date Signed